

OPA Spill Response Kit: HC04OPA

Instructions:

- Use two (2) jugs per one (1) gallon of solution
- Check MSDS for proper attire
- Pour powder around perimeter of spilled sterilant
- Pour remainder of powder in the center, on top of spilled sterilant
- Wait fifteen (15) minutes to remove neutralized solution
- Dispose by scooping/sweeping into a Hazardous Waste Container